ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 6 | Thanisandra |

| Street ID | Street Name | Significant Landmark |
|---|---|---|
| W0035, W0020, W0029, W0019, W0043, W0037 | NA | Hegdenagara |

| Segment No. | Total Length (m) |
|---|---|
| 6/C-W0035/S033246 | 198.75 |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 198.75 | 77.628235 | 13.070172 | 77.630034 | 13.069919 | Hegdenagara | 2nd main road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements of drains and construction of RCC culverts at Hegdenagara in ward no. 06 Byatarayanapura | 1500000 | 2018-19 |

| Year | Type of Work | Other Work Type |
|---|---|---|
| 2018 - 2019 | Others | Flagging course and kerb and covering slab |

| Tender | Work Details | Job No. / Work Code |
|---|---|---|
| Tender | | 006-19-000011 |

| Work Order No. | Work Order Date | Period of Extention |
|---|---|---|
| EE(Project)Ynk Zone/WO/132/2019 | 13/12/2019 | |

| Defect Liability Period From | Defect Liability Period To | Multiple road involved with the same Job No/ Work Code # |
|---|---|---|
| 13/12/2019 | 13/12/2021 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| P. Hemanth | | 0.00 |

| Phone No. | E-Mail ID |
|---|---|
| 9448081837 | |

Zone: YELAHANKA Ward No: 6 Ward Name: Thanisandra Street ID: W0035, W0020, W0029, W0019,

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | srinivasalu |
| **Date of Inspection** | **Remarks** | |
| 15/02/2020 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition |  | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Sri.S.P.Ranganath | 18/02/2020 | 16/03/2020 | As proposed |
| SE | Vijayakumar Haridasu | 18/02/2020 | 16/03/2020 | As Proposed |
| EE | Yerappareddy | 15/02/2020 | 16/03/2020 | approved |
| AEE | K.R.Chidananda | 15/02/2020 | 16/03/2020 | Mobile verification is done |
| AE | Srinivasalu | 15/02/2020 | 16/03/2020 | Mobile verification is done |
| AE | Srinivasalu | 15/02/2020 | 16/03/2020 | Forwarded |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0035, W0020, W0029, W0019,

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore